



c.p. ALLSTAR CORPORATION
 PO Box 240
 Downingtown, PA 19335

TOLERANCE
 (UNLESS NOTED)
 X.X ±0.030
 X.XX ±0.020
 X.XXX ±0.010

APPROVED BY
 SCALE
 1:1

DRAWN BY
 DCG

DATE
 09.16.05

SHT
 4 OF 6

MATERIAL
 N/A

FRACTIONAL
 ±1/32

ANGULAR
 ±1°

TITLE
 Wiring Diagram, 3-Phase Motor, CDO MCB, 2005

DWG NO.
 112757

REV
 B

OPERATING MODES SWITCH SETTINGS

MODE	S1	S2	S3	S4
C2	OFF	OFF	OFF	OFF
B2	ON	OFF	OFF	OFF
D1	OFF	ON	OFF	OFF
E2	ON	ON	OFF	OFF
TS	OFF	OFF	ON	OFF
T	ON	OFF	ON	OFF

ON BOARD OPEN/CLOSE/ STOP CONTROL BUTTONS

* REMOVE FACTORY JUMPER
 IF USING NC REV INPUT

**THREE PHASE
 MOTOR
 208/230/460 VAC**

